

Test Report No.: SZXEC25002751513 **Date**: Aug 05, 2025 Page 1 of 4

Client Name: SHENZHEN LUGUANG ELECTRONIC TECHNOLOGY CO.,LTD.

RIZHAO LUGUANG ELECTRONIC TECHNOLOGY CO.,LTD.

Client Address: 1407, B BLOCK, HAISONG BUILDING, TERRA 9 RD, FUTIAN

DISTRICT, SHENZHEN, CHINA

166, GUILIN ROAD, RIZHAO ECONOMIC DEVELOPMENT ZONE SHANDONG

PROVINCE

Sample Name: Glass-sealed diode

Model No.: MINIMELF

Client Ref. Information: MELF, MINI MELF, MICRO MELF, LL34, LL-41,

DO-34,DO-35,DO-41G,SOD-80,QUADROMELF

The above sample(s) and information were provided by the client.

SGS Job No.: SZP25-038832 Sample Receiving Date: Jul 30, 2025

Testing Period: Jul 30, 2025 ~ Aug 05, 2025

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

Test Requirement	Conclusion
Halogen	See Results

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

May

May Bei

Approved Signatory





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck@sgs.com

Room 101-901, Pant 4 & Room 101, Pant 2 & Room 101, Pant 3 & Room 301-501, Pant 3, Jacques (Banfan) Industrial Plant Area, No. 430, Jihua Rood, Sanfan Community, Banfan Street, Longsang Distric, Shenzhen, Guangdong, China 18129 www.sepsgroup.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江薫(坂田)工业厂区厂房4号101-901、2号101、3号301-501 庫编:518129 (168-755) 25328888 sgs.china@sgs.com



Test Report No.: SZXEC25002751513 **Date**: Aug 05, 2025 Page 2 of 4

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A3	SZX25-0027515-0001.C003	"Glass-sealed diode"

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A3
Fluorine(F)	mg/kg	20	ND
Chlorine(CI)	mg/kg	50	ND
Bromine(Br)	mg/kg	50	ND
lodine(I)	mg/kg	50	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Roum 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 2 & Room 101, Plant 3, Room 301-301, Plant 3, Langhao Bendian) Industrial Plant Area, No. 403, Illiua Read, Barifae Community, Bantian Steet, Longsang Districk, Shenzhen, Guanpdong, China 181812 www.sepsgroup.com.cn 中国 - 广东 - 深圳市龙岗区坂田街道坂田社区吉年路430号江瀛(坂田)工业厂区厂房4号101-901、2号101、3号301-501 樟编:518129 t(86-755) 25328888 sps.china@sps.com



Test Report ATTACHMENTS

Halogen Testing Flow Chart





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com



Test Report No.: SZXEC25002751513 **Date**: Aug 05, 2025 Page 4 of 4

Sample Photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Roum 101-901, Plant 44 Rhoum 101, Plant 24 Rhoum 101, Plant 24 Rhoum 101, Plant 34 Rhoum 101-901, Plant 34 Rhoum 101-901, Plant 34 Rhoum 101-901, 29-101, 39-301-501 章编:518129 www.sgs-group.com.cn中国 - 广东·深圳市龙岗区坂田街道坂田社区吉华森430号江灏(坂田)工业厂区厂房4号101-901, 29-101, 39-301-501 章编:518129 t(86-755) 25328888 sgs.china@sgs.com